

Policy Unit: 5f PHB10

Holes Bay (E, N & W)



Summary

This unit contains Holes Bay, a large tidal harbour with a narrow entrance which is largely reclaimed land and developed in most parts. It is fringed by mud and saltmarsh with a railway line protected by embankments bisecting the bay in the north. The bay is considered to be low energy with the north end in particular showing no signs of coastal erosion. This section of the bay is backed by natural bank whilst the remainder is a mixture of concrete defences and rock revetment.

Survey Regime

Survey type	Frequency	Profile spacing/survey extent
<i>Topographic interim profiles</i>	N/A	N/A
<i>Topographic baseline</i>	N/A	N/A
<i>Bathymetric baseline</i>	N/A	N/A
<i>Ortho-photography</i>	5 years	MLW
<i>Non-rectified aerial photography</i>	Annual	MLW
<i>Lidar</i>	3 years	MLW
<i>Habitat mapping</i>	5 Years	As Required